

Uva Wellassa University of Sri Lanka
Faculty of Science and Technology
Department of Science and Technology
400 level 1st Semester Examination - June/July 2017
SCT 467-2 Computer Aided Design & Manufacturing



1.

- a. Compare the terms CAD, CAM & CIA. (05 marks)
- b. State four elements of CIM system. (04 marks)
- c. Draw a diagram of a product life cycle and discuss its major stages, and discuss at which point manufacturer should need to think about changing their products. (08 marks)
- d. Differentiate between sequential engineering and concurrent engineering. (08 marks)

2.

- a. State steps of engineering design process. (05 marks)
- b. Write the G-code program for the following part shown in figure 01 considering the points given below. (20 marks)

- a. Use the given points as the part coordinate zero point
- b. Thickness of the part is 5 mm and you have given 5 mm metal sheet to cut the part
- c. Only one run is needed to cut a line
- d. Use absolute coordinate system
- e. Use 8 mm end mill cutter
- f. Refer G-Codes in the end of the exam paper




Figure 01

3.

Design appropriate CNC machining operation sequence for the given "Solidwork" part in figure 02 named "Ex2017" using "SolidCAM". Define rectangular stock material of 5 mm from all side. Use appropriate part coordinate systems. The part file will be available in your common folder.

(50 marks)





Figure 02



G00 - Positioning at rapid speed; Mill and Lathe
 G01 - Linear interpolation (machining a straight line); Mill and Lathe
 G02 - Circular interpolation clockwise (machining arcs); Mill and Lathe
 G03 - Circular interpolation, counter clockwise; Mill and Lathe
 G04 - Mill and Lathe, Dwell
 G09 - Mill and Lathe, Exact stop
 G10 - Setting offsets in the program; Mill and Lathe
 G12 - Circular pocket milling, clockwise; Mill
 G13 - Circular pocket milling, counterclockwise; Mill
 G17 - X-Y plane for arc machining; Mill and Lathe with live tooling
 G18 - Z-X plane for arc machining; Mill and Lathe with live tooling
 G19 - Z-Y plane for arc machining; Mill and Lathe with live tooling
 G20 - Inch units; Mill and Lathe
 G21 - Metric units; Mill and Lathe
 G27 - Reference return check; Mill and Lathe
 G28 - Automatic return through reference point; Mill and Lathe
 G29 - Move to location through reference point; Mill and Lathe (slightly different for each machine)
 G31 - Skip function; Mill and Lathe
 G32 - Thread cutting; Lathe
 G33 - Thread cutting; Mill
 G40 - Cancel diameter offset; Mill. Cancel tool nose offset; Lathe
 G41 - Cutter compensation left; Mill. Tool nose radius compensation left; Lathe
 G42 - Cutter compensation right; Mill. Tool nose radius compensation right; Lathe
 G43 - Tool length compensation; Mill
 G44 - Tool length compensation cancel; Mill (sometimes G49)
 G50 - Set coordinate system and maximum RPM; Lathe
 G52 - Local coordinate system setting; Mill and Lathe
 G53 - Machine coordinate system setting; Mill and Lathe
 G54~G59 - Workpiece coordinate system settings #1 to #6; Mill and Lathe
 G61 - Exact stop check; Mill and Lathe
 G65 - Custom macro call; Mill and Lathe
 G70 - Finish cycle; Lathe
 G71 - Rough turning cycle; Lathe
 G72 - Rough facing cycle; Lathe
 G73 - Irregular rough turning cycle; Lathe
 G73 - Chip break drilling cycle; Mill
 G74 - Left hand tapping; Mill
 G74 - Face grooving or chip break drilling; Lathe
 G75 - OD groove pecking; Lathe
 G76 - Fine boring cycle; Mill
 G76 - Threading cycle; Lathe
 G80 - Cancel cycles; Mill and Lathe
 G81 - Drill cycle; Mill and Lathe
 G82 - Drill cycle with dwell; Mill
 G83 - Peck drilling cycle; Mill
 G84 - Tapping cycle; Mill and Lathe
 G85 - Bore in, bore out; Mill and Lathe
 G86 - Bore in, rapid out; Mill and Lathe
 G87 - Back boring cycle; Mill
 G90 - Absolute programming

- G91 - Incremental programming
- G92 - Reposition origin point; Mill
- G92 - Thread cutting cycle; Lathe
- G94 - Per minute feed; Mill
- G95 - Per revolution feed; Mill
- G96 - Constant surface speed control; Lathe
- G97 - Constant surface speed cancel
- G98 - Per minute feed; Lathe
- G99 - Per revolution feed; Lathe

CNC M Codes

- M00 - Program stop; Mill and Lathe
- M01 - Optional program stop; Lathe and Mill
- M02 - Program end; Lathe and Mill
- M03 - Spindle on clockwise; Lathe and Mill
- M04 - Spindle on counterclockwise; Lathe and Mill
- M05 - Spindle off; Lathe and Mill
- M06 - Toolchange; Mill
- M08 - Coolant on; Lathe and Mill
- M09 - Coolant off; Lathe and Mill
- M10 - Chuck or rotary table clamp; Lathe and Mill
- M11 - Chuck or rotary table clamp off; Lathe and Mill
- M19 - Orient spindle; Lathe and Mill
- M30 - Program end, return to start; Lathe and Mill
- M97 - Local sub-routine call; Lathe and Mill
- M98 - Sub-program call; Lathe and Mill
- M99 - End of sub program; Lathe and Mill

- A A-axis command (usually a rotary)
- B B-axis command (usually a rotary)
- C C-axis command (usually a rotary)
- D Tool diameter/radius compensation number
- F Feedrate value
- G CNC function or code
- H Tool length compensation number
- I Circle center distance for X
- J Circle center distance for Y
- K Circle center distance for Z or circle radius (G12/G13)
- L Loop count for subroutine/macro
- M Machine function or code
- N Block sequence number
- P Macro programming variable
- Q Subroutine program number to call
- R Rotation or scaling factor
- S Spindle speed (RPM)
- T Tool number or turret position
- X X-axis command (usually a linear)
- Y Y-axis command (usually a linear)
- Z Z-axis command (usually a linear)

